




全校廁所、盥洗室及更衣室防針孔檢測表(112年2月)

| 場館名稱 | 廁所數量(包含男女) | 偵測結果 | 盥洗室及更衣室數量(包含男女) | 偵測結果 | 現場照片 | |
|------|------------|------|-----------------|------|--|---|
| 力行樓 | 8 | ○ | 2 | ○ |  |  |
| 研究大樓 | 6 | ○ | 6 | ○ |  |  |
| 至真樓 | 4 | ○ | 2 | ○ |  |  |
| 資訊館 | 2 | ○ | / | / |  |  |
| 活動中心 | 2 | ○ | / | / |  |  |
| 大禮堂 | 2 | ○ | / | / |  |  |

| | | | | | | |
|---------------|-----|---|---|---|--|---|
| 消防大樓 | 未開放 | | | | | |
| 舊科學館 | 8 | ○ | | |  |  |
| 博物館 (B3、4) | 4 | ○ | | |  |  |
| 靶場 | 5 | ○ | 1 | ○ |  | |
| | | | | |  | |
| 游泳池 | 2 | ○ | 2 | ○ | 未開放 | |
| 警技館 | 21 | ○ | 6 | ○ |  |  |
| 射擊館 | 15 | ○ | 0 | ○ |  | |

| | | | | | | |
|------|-----|---|----|---|--|---|
| | | | | |  | |
| 體育館 | 2 | ○ | 2 | ○ |  |  |
| 司令台 | 未開放 | | | | | |
| 教學大樓 | 36 | ○ | / | / |  |  |
| 警英樓 | 28 | ○ | 14 | ○ |  |  |
| 警賢樓 | 10 | ○ | 10 | ○ |  |  |
| 友誼樓 | 21 | ○ | 17 | ○ |  |  |

| | | | | | | |
|---------|-----|---|----|---|--|---|
| 警光樓 | 17 | ○ | 11 | ○ |  |  |
| 蘭庭 | 施工中 | | | | | |
| 科學館 | 6 | ○ | | |  |  |
| 刑事鑑識大樓 | 16 | ○ | | |  |  |
| 圖書(博物)館 | 13 | ○ | | |  |  |

註：偵測結果正常請打「○」，有異常情形請打「X」